



Product Name: 908

Current Version:

Ver.Type	Ver No.	Date
Firmware	R2.0.32306	December 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 2016

Reference: 11490

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
908	Any	Yes	N/A

Technical Notes:

- Volume issues were fixed.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: 908

Current Version:

Ver.Type	Ver No.	Date
Firmware	R2.0.32306	December 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: December 2016

Reference: 11490

The following changes were made in this version:

Bugs Fixed:

QC ID	Description
9233	Volume level was set to "0" after cycling the power
9235	Did not generate volume feedback when rotating the knob in UTP. TCP worked correctly

Bugs to be Fixed in Future Version:

QC ID	Description
6557	Web page is not open with win7

Known Limitations (including compatibility limitations):

QC ID	Description
9234	Open 2 TCP connections with the 908 causing PING lost with the device (after a while the, 908 follow a "watch dog" and resume ETH connectivity)

Preceding Version: F – 1.13.23329



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: 908
Preceding Version: F – 1.13.23329
Version Date: October 2015
Reference: 9569

The following changes were made in this version:

Fixes:

- Last active input is remembered at power off.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com