

## Release Notes

**Product Name:** Kramer BRAINware

| Current Version: | Ver.Type | Ver No. | Date       |
|------------------|----------|---------|------------|
|                  | Firmware | –       | –          |
|                  | Software | V1.3.3  | April 2018 |
|                  | Web      | –       | –          |
|                  | Hardware | –       | –          |

**RN Date:** April 2018

**Reference:** 133

### Kramer Product Affected:

| Product Name     | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|------------------|--------------------------------|---------------------------|-------------------------------------|
| Kramer BRAINware | N/A                            | Yes                       | N/A                                 |
|                  |                                |                           |                                     |

### Technical Notes:

- Fixed several bugs.

### Codependency with Other Products and Software:

| Product Name | Comments |
|--------------|----------|
| KT-107       |          |
| KT-107RB     |          |
| KT-107S      |          |



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** Kramer BRAINware

| <b>Current Version:</b> | Ver.Type | Ver No. | Date       |
|-------------------------|----------|---------|------------|
|                         | Firmware | –       | –          |
|                         | Software | V1.3.3  | April 2018 |
|                         | Web      | –       | –          |
|                         | Hardware | –       | –          |

**RN Date:** April 2018

**Reference:** 133

The following changes were made in this version:

### Bugs Fixed:

| Component | Fixed Bug Description   |
|-----------|---|
|           | Lost UDP connections create a scenario where new socket connections cannot be properly made on the Network. |
|           | UDP multicast and broadcast connection not being made properly.   |
|           | System Device Custom States could not be used as a Reference device in another Space.                       |

### Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description   |
|-------|--|
|       | Bug:<br>IP change on DHCP mode.<br><br>Workaround:<br>Assign KT-107 a static IP address; either on the router (if using DHCP) or in the Ethernet settings on the tablet itself (if wired). |

### Known Limitations (including compatibility limitations):

| Component | Limitation Description |
|-----------|------------------------|
|           | None listed.           |

**Preceding Version:** S – 1.3



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** Kramer BRAINware

**Current Version:**

| Ver.Type | Ver No. | Date       |
|----------|---------|------------|
| Firmware |         | -          |
| Software | 1.3     | March 2018 |
| Web      | -       | -          |
| Hardware | -       | -          |

**RN Date:** March 2018

**Reference:** 13865

### Kramer Product Affected:

| Product Name     | Minimum FW Version for Upgrade | Recommended for All Units | Only if Added Features are Required |
|------------------|--------------------------------|---------------------------|-------------------------------------|
| Kramer BRAINware | N/A                            | N/A                       | N/A                                 |

### Technical Notes:

- This is a release note for a new product.

### Codependency with Other Products and Software:

| Product Name | Comments |
|--------------|----------|
| KT-107       |          |
| KT-107RB     |          |
| KT-107S      |          |



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes History

**Product Name:** Kramer BRAINware

| <b>Current Version:</b> | Ver.Type | Ver No. | Date       |
|-------------------------|----------|---------|------------|
|                         | Firmware |         | -          |
|                         | Software | 1.3     | March 2018 |
|                         | Web      | -       | -          |
|                         | Hardware | -       | -          |

**RN Date:** March 2018

**Reference:** 13865

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/Kramer BRAINware>

### Bugs to Fix in Future Versions:

| QC ID | Deferred Bug Description   |
|-------|--|
|       | Bug:<br>IP change on DHCP mode.<br><br>Workaround:<br>Assign KT-107 a static IP address; either on the router (if using DHCP) or in the Ethernet settings on the tablet itself (if wired). |

### Known Limitations (including compatibility limitations):

| QC ID | Limitation Description |
|-------|------------------------|
|       | None listed.           |

**Preceding Version:** S – N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)