Product Name: VS-62H

Current Version: F – 2.0.16265

Version Date: December 2014

Reference: 8041

Release Type:

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-62H	Any	Yes	N/A

Technical Notes:

- Support for SID-X3N was added.

Codependency with Other Products and Software:

- There is no codependency with other products or software.

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: VS-62H

Current Version: F – 2.0.16265

Version Date: December 2014

Reference: 8041

The following changes were made in this version:

Added Features:

- Support for the SID-X3N was added.

Known Issues:

- When using the pattern generator, non-RGB content connected to input 6 may cause issues in image stability.
- MUTE doesn't work from the front panel in Function mode. From the Web it is OK.

Preceding Version: F – 1.1.15803

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: VS-62H

Preceding Version: F – 1.1.15803

Version Date: September 2014

Reference: 7804

The following changes were made in this version:

Fixes:

- Auto-switch mode sometimes caused random input switching.

Known Issues:

- When using the pattern generator, non-RGB content connected to input 6 may cause issues in image stability.
- MUTE doesn't work from the front panel in Function mode. From the Web it is OK.
- There are some compatibility issues when working with SID-X3 as a step-in device in auto switching mode

Preceding Version: NP – 1.0

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com

Product Name: VS-62H

Preceding Version: NP – 1.0

Version Date: May 2014

Reference: 4381

This is a release note for a new product.

Known Issues:

- When using the pattern generator, non-RGB content connected to input 6 may cause issues in image stability.
- MUTE doesn't work from the front panel in Function mode. From the Web it is OK.
- There are some compatibility issues when working with SID-X3 as a step-in device in auto switching mode

Preceding Version: N/A

KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com