



**Product Name:** FC-10ETH  
**Current Version:** F – 3.0.18181  
**Version Date:** June 2015  
**Reference:** 8640

**Release Type:**

☒ Firmware ☐ Software ☐ Hardware ☐ New Product

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
FC-10ETH	Any	Yes	N/A

**Technical Notes:**

- Baud rate issues were fixed.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramereel.com](mailto:info@kramereel.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)



**Product Name:** FC-10ETH  
**Current Version:** F – 3.0.18181  
**Version Date:** June 2015  
**Reference:** 8640

The following changes were made in this version:

**Fixes:**

- The RS-232 configuration did not support baud rates different from 9600 or 115200 bps.
- RS-485 connection only worked at 9600 bps.

**Known Issues:**

- There are no known issues.

**Preceding Version:** F – 2.0.8779



KRAMER ELECTRONICS, Ltd.

E-mail: [info@kramerelect.com](mailto:info@kramerelect.com)

Web: [www.kramerelectronics.com](http://www.kramerelectronics.com)