



Product Name: RC-74DL
Current Version: F – 4.0.29.25028
Version Date: April 2016
Reference: 10433

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
RC-74DL	Any	Yes	N/A

Technical Notes:

- A protocol command problem was fixed.

Codependency with Other Products and Software:

Product Name	Comments
K-Config 3	Ver 3.1.1.3



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: RC-74DL
Current Version: F – 4.0.29.25028
Version Date: April 2016
Reference: 10433

The following changes were made in this version:

Fixes:

- After a few attempts, RC-74DL stopped sending some protocol commands.

Known Issues:

There are no known issues

Preceding Version: F – 4.0.29.24637



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: RC-74DL
Preceding Version: F – 4.0.29.24637
Version Date: February 2016
Reference: 10059

The following changes were made in this version:

Modifications:

- Support for K-Config 3 features.

Known Issues:

There are no known issues

Preceding Version: F – 4.0.15.11355



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: RC-74DL
Current Version: F – 4.0.15.11355
Version Date: March 2014
Reference: 6364

The following changes were made in this version:

Added Features:

Added support for K-Config 2 new relevant features:

- K-Config 2 – Support for new queries mechanism
- K-Config 2 – Supports new tables
- K-Config 2 – Supports new DELAY
- K-Config 2 – Supports “Test command”
- K-Config 2 – Support 10 Ethernet clients

Fixes:

- Various bugs were fixed and performance stabilized.

Modifications:

- Speed enhancements were made.

Known Issues:

- There are no known issues.

Preceding Version: 3.5.1.7535



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerelect.com

Web: www.kramerelectronics.com



Preceding Version: 3.5.1.7535

Version Date: December 2012

Reference: 4157

The following changes were made in this version:

Added Features:

- Syncing the internal clock with an external time server is now supported (requires K-Config 1.0.3.37).

Fixes:

- Multiple communication errors were corrected.
- Multiple operation errors were corrected.
- Web page errors were corrected (when using the new K-Config 1.0.3.37).

Known Issues:

- In rare cases, writing a new configuration fails. If this happens, perform a factory reset and retry the writing. The next release of K-Config software fixes this bug.
- When Sync Time from the time server is ON and all three control Ethernet sockets are set to UDP (in the K-Config 1.0.3.37 port manager), the device might hang. Avoid this setup. To recover, perform a factory reset and use a different setup.

Preceding Version: 3.4.1.6522



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Preceding Version: 3.4.1.6522

Version Date: August 2012

Reference: 3395

The following changes were made in this version:

Fixes:

- A problem with the device hanging after receiving a long IR signal was fixed.
- Fixes were made to the capacity of the scheduler.

Known Issues:

- In rare cases, writing a new configuration fails. If this happens, perform a factory reset and retry the writing.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Preceding Version: N/A

Version Date: March 2012

Reference: 2503

The following changes were made in this version:

Fixes:

- A problem with configured buttons not flashing was corrected. They now flash as configured.

Known Issues:

- There are no known issues.

Preceding Version: 1.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com