



Product Name: SL-12

Current Version:	Ver.Type	Ver No.	Date
	Firmware	4.0.33.29083	August 2016
	Software	–	–
	Web	–	–
	Hardware	–	–

RN Date: August 2016

Reference: 11012

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SL-12	Any	Yes	N/A

Technical Notes:

- Support for new flash component.
- Improved PJLINK protocol handling.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: SL-12

Current Version:

Ver.Type	Ver No.	Date
Firmware	4.0.33.29083	August 2016
Software	–	–
Web	–	–
Hardware	–	–

RN Date: August 2016

Reference: 11012

The following changes were made in this version:

New Features:

	Description
	Support for new flash component
	Improved PJLINK protocol handling

Known Limitations (including compatibility limitations):

QC ID	Description
2154	Cannot read/control analog/digital IO (GPIO) on AUX device
3559	38KHz IR frequency support

Preceding Version: F – 4.0.29.24637



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramere.com

Web: www.kramerelectronics.com



Product Name: SL-12
Current Version: F – 4.0.29.24637
Version Date: February 2016
Reference: 10067

The following changes were made in this version:

Modifications:

- Support for K-Config 3 features.

Known Issues:

- There are no known issues.

Preceding Version: F – 4.0.15.11355



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: SL-12
Preceding Version: F – 4.0.15.11355
Version Date: March 2014
Reference: 6935

The following changes were made in this version:

Added Features:

Added support for K-Config 2 new relevant features:

- K-Config 2 – Support for new queries mechanism
- K-Config 2 – Supports new tables
- K-Config 2 – Supports new DELAY
- K-Config 2 – Supports “Test command”
- K-Config 2 – Support 10 Ethernet clients

Fixes:

- Various bugs were fixed and performance stabilized.

Modifications:

- Speed enhancements were made.

Known Issues:

- There are no known issues.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com