

## Release Note

**Product Name:** VS-411UHD

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	1.0	June 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 2017

**Reference:** 10329

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-411UHD	N/A	N/A	N/A

### Technical Notes:

- This is a release note for a new product.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note History

**Product Name:** VS-411UHD

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	1.0	June 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** June 2017

**Reference:** 10329

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/VS-411UHD>

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
11153	Error when trying to copy an EDID to all outputs
11154	Error when trying to copy the default EDID
11155	Error when trying to copy external EDID

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
6741	Deembedded analog audio exists when non-HDCP SINK connected or no SINK connected at all, when an encrypted Embedded HDMI is the input
6742	Audio exists when HDCP is disabled on input and the input signal is encrypted when the SINK is HDCP
6744	There is no option to choose the priority order when choosing the priority mode

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)