

Release Note

Product Name: VS-84UHD

Current Version:

Ver.Type	Ver No.	Date
Firmware	1.2_0001 1.2.2	January 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 2018

Reference: 11778

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-84UHD	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Note History

Product Name: VS-84UHD

Current Version:

Ver.Type	Ver No.	Date
Firmware	1.2_0001 1.2.2	January 2017
Software	–	–
Web	–	–
Hardware	–	–

RN Date: January 2017

Reference: 11778

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/VS-84UHD>

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
12264, 12267	WEB page message improvements are required
12266	Protocol 3000 #vmute command implemented with opposite enable/disable = 0/1 polarity.
12268	A failed Firmware upgrade due to accidental power shutdown requires system recovery sequence. Please contact Kramer technical support for information.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com