

## Release Note

**Product Name:** VS-88UHD

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	1.1	October 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** October 2017

**Reference:** 11446

**Kramer Product Affected:**

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VS-88UHD	N/A	N/A	N/A

**Technical Notes:**

- This is a release note for a new product.

**Codependency with Other Products and Software:**

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note History

**Product Name:** VS-88UHD

**Current Version:**

Ver.Type	Ver No.	Date
Firmware	1.1	October 2017
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** October 2017

**Reference:** 11446

This is a release note for a new product. For a list of new product features see:

<http://www.kramerav.com/manual/VS-88UHD>

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
11603	When UDP port is changed from the default 50,000, Kramer Network does not automatically discover the device
11604	When TCP port is changed from the default 5,000, Kramer Network does not automatically discover the device
11744	Protocol 3000: Illegal gateway address in #NET-IP command returns “error 10” instead of expected “error 04”
11749	In Last Connected and Priority switching modes, switching may take longer than 3 seconds after disconnecting an input

### Known Limitations (including compatibility limitations):

- None listed.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)