



Product Name: K-Router Plus

Preceding Version: S – 2.0.38

Version Date: March 2016

Reference: 8732

Release Type:

Firmware Software Hardware New Product

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
K-Router Plus	N/A	N/A	N/A

Technical Notes:

- Support was added for the VS-3232DN.

Codependency with Other Products and Software:

Product Name	Comments
VS-88HN and VS-88HDCPxI families	K-Router Plus only works with Protocol 3000. IR control does not work on the codependent products when the product is set to Protocol 3000 or controlled by K-Router Plus. To control the product using IR, the product must set to Protocol 2000 and use the previous version of K-Router.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: K-Router Plus
Preceding Version: S – 2.0.38
Version Date: March 2016
Reference: 8732

The following changes were made in this version:

Added Features:

- Support was added for the VS-3232DN.

Known Issues:

- K-Router Plus only works with Protocol 3000. IR control does not work on the codependent products when the product is set to Protocol 3000 or controlled by K-Router Plus. To control the product using IR, the product must set to Protocol 2000 and use the previous version of K-Router.

Preceding Version: S – 2.0.30.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: K-Router Plus
Preceding Version: S – 2.0.30.0
Version Date: August 2014 (Rev 2)
Reference: 7255

Fixes:

- The machine configuration was correctly restored on the application GUI.
- Firmware update was not available for the VS-88HFS.
- K-Router Plus now reads the EDID file correctly from all devices, in both TCP and serial modes.

Known Issues:

- K-Router Plus only works with Protocol 3000. IR control does not work on the codependent products when the product is set to Protocol 3000 or controlled by K-Router Plus. To control the product using IR, the product must set to Protocol 2000 and use the previous version of K-Router.
- On the VS-1616D and the VS-3232D, K-Router Plus works via Ethernet only with new Fast Switching firmware. RS-232 works with any firmware Contact your local Kramer office for details.

Preceding Version: S – 2.0.28.0



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerel.com

Web: www.kramerelectronics.com



Product Name: K-Router Plus
Preceding Version: S – 2.0.28.0
Version Date: February 2014
Reference: RD-001026

Known Issues:

- K-Router+ only works with Protocol 3000. IR control does not work on the codependent products when the product is set to Protocol 3000 or controlled by K-Router+. To control the product using IR, the product must set to Protocol 2000 and use the previous version of K-Router.

Preceding Version: S – N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramereel.com

Web: www.kramerelectronics.com